

# SILPAK R-1348

## Firm Tin RTV Silicone System

R-1348 is a 40 Shore A, Tin Base (condensation cure), two-component, room temperature cure (RTV) rubber designed for general purpose applications where a low shrink, firm rubber mold or part is required. Its consistent curing characteristics, excellent shelf life, and outstanding physical properties make it a product that can easily meet a wide variety of applications. Use to cast foam, polyester, urethane, epoxy, low melt metal (350°F), thermoplastics (polyvinyl), wax, soap, plaster, and any material where a release free casting is required.

### Features

- Extra firmness for casting urethane foam parts
- Excellent physical properties with high tear resistance
- Good polyester and urethane resin resistance

### Applications

Use to molds cast foam, polyester, urethane, epoxy, low melt metal (350°F), thermoplastics (polyvinyl), wax, soap, plaster, and any material where a release free casting is required.

- Production molds

### Physical and Handling Properties of Cured Rubber

Property	Value
Color	Off-White Base; Orange Activator
Mix Ratio, by weight	100 Base:5 Activator
Initial Viscosity, Base, cP	45,000
Initial Viscosity, Activator, cP	50
Initial Mixed Viscosity, at 77°F, cP	40,000
Hardness, Shore A	40
Pot Life, min	60
Demold Time, hr	8-10
Specific Gravity	1.15
Tensile Strength, psi	500
Elongation, %	350
Tear Resistance, pli	170

*Values listed above are typical and not intended for use in specifications.*

## Proper Use and Safety

Read all instructions and safety data sheets prior to use. Consult safety data sheets for all recommended safety precautions.

## Mixing & Curing

Activator should be shaken prior to use. Add the activator to the base. The addition of 10% activator (by weight) has a pot life of 30-45 minutes and is ready for de-molding after 6 hours. R-1348 Activator has a trace of pigment for a visual check of adequate mixing. Degassing material is always recommended. Immediately after mixing, place the material in a vacuum chamber to remove trapped air and allow enough room for expansion as vacuum is drawn, as much as four times its original volume. Remove from vacuum chamber and pour very gently into cavity so as not to re-incorporate air into the material. After the mold has been removed from the master, it should be left for 24 hours to develop its maximum mechanical strength.

## Brush On Molds

For brush-on molds, use **Silpak R-1300TH Red Activator** (slower), **Silpak R-1324<sup>th</sup> Blue Activator** (faster), or **Silpak PE-ESS-5F Mini Fibers** in place of the pour Activator. The first coat (detail/print coat) should be applied using the **Silpak R-1324 Blue Activator**, this Activator sets up quicker in thin sections. Mix a small batch and paint on the first layer, ensuring that the entire model is covered. Material will drip and pool around the base of model so a dam made of clay or cardboard should be made to contain leaks. Once material has gelled, 30-45 minutes later, the brush on coat can be applied. Continue to build mold wall thickness by applying one coat after another, about an hour apart. This may take several coats, but the goal is to achieve a mold wall thickness of 3/8 to 1/2 inch. It is recommended when building a brush-on mold to complete it within 24 hours to avoid any adhesion problems between layers. Keep mold covered to avoid dust contamination that could affect the adhesion between coats. Hot summer weather could shorten work time. Once rubber mold has been completed and is fully cured, the process of building a support mold made of plaster (**Silpak Castshell**), fiberglass (**Silpak SLR-22**) or urethane plastic (**Silpak Trowel On 60**) to hold the thin rubber mold bladder is undertaken. **Note:** Also available is **Silpak Thix 5170 Additive** to create brush-on, low sag, rubber bladders.

## Storage and Shelf Life

Base and Activator must be stored in their original, tightly closed containers to protect from moisture and foreign materials. Storage area should be maintained at temperatures between 64-86°F. Shelf life of materials when kept in unopened, sealed containers, at the recommended storage conditions, is six months. Containers should not be opened until ready or use. Once opened, storage life can be extended with the use of purging gas, such as nitrogen.

*DISCLAIMER: the information and data contained herein are based on information we believe is reliable. Each user of the material should thoroughly test application, and independently conclude satisfactory performance before commercializing. Suggestions of uses should not be taken as inducements to infringe on any patent. Silpak or Polytek Development Corp make no warranty expressed or implied, including warranties of merchantability or fitness for a particular use. Under no circumstances will Silpak or Polytek Development Corp. be liable for incidental, consequential or other damages, alleged negligence, breach of warranty, strict liability, tort, or any other legal theory arising out of the use or handling of this product.*